

Check the level of humidity in your materials

- Ideal for detecting leaks
- Functions with all construction materials: wood, plaster, brick, etc.
- 2 x 20 LED display scales



PHYSICS

Line

C.A 847

Materials
Moisture Meter

Hygrometry

Measurement range	6 to 100 % of degree of moisture
2 display scales	6 to 23 %
	24 to 100 %

- ✓ Low battery indication
- ✓ Protective shock-proof sheath

Operating conditions:

- Temperature: 0 to 50 °C
- Humidity: < 80 % RH

Dimensions: 195 x 60.5 x 38 mm

Mass: 160 g

Storing conditions:

- Temperature: -20 °C to +60 °C
- Humidity: < 80 % RH

Power supply: 1 x 9 V battery

Replaceable electrodes
(L = 12 mm)



To order


C.A 847 Materials Moisture Meter	P01.1563.02Z
----------------------------------	--------------



HVAC systems



Electrical,
Mechanical
Maintenance



Storage



Logistics



Museums,
Libraries,
Archives